

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Oakley Environmental Engineer				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0150018		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, June 24, 2010		
Start Date/Time:	6/24/2010 9:00:00 AM		
End Date/Time:	6/24/2010 1:00:00 PM		
Last Inspection:	Tuesday, May 04, 2010		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 76 Deg. F. InspectionID Report Number: 2409

Accepted by: jhelfric

6/29/2010

Permitee: PacifiCorp

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted		
Total Disturbed	98.05	
Phase I	0.60	
Phase II		
Phase III		

Mineral	Ownership	
---------	-----------	--

Types of Operations ✓ Underground **Federal** ☐ Surface State County Loadout Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Other

Inspector's Signature:

Date

Thursday, June 24, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Thursday, June 24, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures		· 🔲		
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
<u>7.</u>	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Thursday, June 24, 2010

Page 3 of 3

2. Signs and Markers

The mine identification signs are located at the points of public access to the permit area. The signs contained the required information.

8. Noncoal Waste

Noncoal waste was present in the main parking area, along the access road to the main facilities and around the noncoal waste disposal facility. The noncoal waste needs to be gathered and placed in the appropriate storage facility.